

This Page Is Inserted by IFW Operations
and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

**As rescanning documents *will not* correct images,
please do not report the images to the
Image Problem Mailbox.**

108260" 00099660




Fig.1

0966000-092801
F08260" 00099660




Fig.2




Fig.3

09966000 092801
T08260" 00099660




Fig. 4A




Fig. 4B

00099650




Fig.5




Fig. 6

0965000 092801 108260" 00093660




Fig.7




Fig.8




Fig. 9A




Fig. 9B




Fig. 9C



SCAN DIRECTION
OF LASER ANNEAL




Fig. 10A




Fig. 10B

0966000-092801




Fig.11




Fig.12

FIG. 13




Fig.13




Fig. 14




Fig. 15A




Fig. 15B

09965000 092801




Fig. 16A




Fig. 16B




Fig. 17




Fig. 18

09965000-092801
108260-00099560




Fig.19




Fig.20